

Report Number	Event Title
---------------	-------------

Quarter: 2015Q1

P-2014-33997	Technical Operability Evaluation initiated on Reactor Regulating System
P-2014-34705	Automatic Box-Up: Unit Boxed-Up on Increased Activity following Slurry Activity
P-2014-35160	System Unavailable: Emergency Water Supply Unavailable
P-2015-00024	System Unavailable: System Does Not Meet Design Intent of Emergency Low Pressure Service Water
P-2015-00575	Reactor Trip: Unit 6 Tripped during SDS2 Maintenance
P-2015-01026	Release to Environment: Potential Release of Hazardous Material
P-2015-01468	Orders to Comply Issued by the Ministry of Labor
P-2015-02757	Technical Operability Evaluation Initiated Regarding Standby Generators
P-2015-02911	System Unavailable: Level 2 Impairment of ECI
P-2015-03730	Matter of Regulatory Interest: "Ready to Start" Lights Were Extinguished for all 056 Standby Generators
P-2015-03739	System Unavailable: Level 1 Impairment of ECI
P-2015-03798	Relief Valve failed to Open during Post Testing
P-2015-03817	Apparent Missed Test: In-core Flux Detector Alignment not Performed by its Late Date
P-2015-04285	System Unavailable: "Does Not Meet Design Intent" Impairment of EWS
P-2015-04800	Unposted Hazard: Tote of Unknown Liquid Placed in Laydown Area
P-2015-05193	Suspect Item: OPG Informed of Potential Substandard Valves by Supplier
P-2015-05913	Reactor Shutdown due to Turbine Trip

Quarter: 2015Q2

P-2015-06503	Apparent Missed Test: RV51 not tested in accordance with the ASME Standard.
P-2015-07868	Technical Operability Evaluation Initiated Regarding High Pressure Instrument Air Compressors
P-2015-08083	Release to Environment: Apparent Release of a Hazardous Substance to the Environment
P-2015-08507	Apparent Missed Test: Fire Protection Test not done by Due Date
P-2015-08527	System Unavailable: Heat Transport System Leakage to Containment
P-2015-09037	Unposted Hazard: Radiation Hazard Sign Removed from Area with Fields in excess of 2.5 mrem/h
P-2015-09242	Apparent Non-compliance with Packaging and Transport of Nuclear Substances Regulations
P-2015-09845	System Unavailable: Heat Transport System Does Not Meet Design Intent Impairment: Two Pressurizing Pumps Unavailable
P-2015-11190	Apparent Missed Test: SDSA Channel Flow Instrument Loop Calibration not Performed without an Approved Deferral in place.
P-2015-11226	Apparent Non-compliance with Packaging and Transport of Nuclear Substances Regulations
P-2015-11293	Release to Environment: Sewage Spill to the Environment
P-2015-11827	Release to Environment: Sewage Spill to the Environment
P-2015-13639	Automatic Box-Up: Unit Boxed-up during Annulus Gas Purge

Quarter: 2015Q3

P-2015-14819	System Unavailable: Heat Transport System Does Not Meet Design Intent Impairment due to Leakage to Containment
--------------	--

Report Number	Event Title
P-2015-15002	Release to Environment: Exceedance of Limit for Daily Average Temperature Difference
P-2015-15854	Apparent Licence Condition Non-compliance: Prior Notification to the CNSC not Performed before Revising OSR Reports
P-2015-16303	Discovery of a Discrepancy in the Heat Transport System Revised Safety Analysis (no impact on current operations)
P-2015-16403	Apparent Licence Condition Non-compliance: Notification of Change in Employment Status of a Certified Person not sent to CNSC within 21 Days as Required by RegDoc 3.1.1
P-2015-16509	Apparent Licence Condition Non-compliance: Notification of Change in Employment Status of a Certified Person not sent to CNSC within 21 Days as Required by RegDoc 3.1.1
P-2015-16749	Apparent Licence Condition Non-compliance: Valve found Not Blocked Correctly per Guaranteed Shutdown State (GSS) Manual
P-2015-17403	Matter of Regulatory Interest: Wiring Deficiency on Heat Transport System Pump
P-2015-17557	Unit 4 Shutdown due to Turbine Trip
P-2015-17963	System Unavailable: Backup Instrument Air Does Not Meet Design Intent Impairment: Two Instrument Air Bottles found Depleted
P-2015-18231	Automatic Box-Up: Unit 4 Boxed-up on One Channel Following Maintenance on a Second Channel
P-2015-18774	Serious Injury: Employee Twisted Ankle in Pothole which resulted in Lost Time Accident
P-2015-19630	System Unavailable: Does Not Meet Design Intent Impairment Declared as Two ELPSW Pumps were Unavailable
P-2015-19975	Automatic Box-Up: Unit Boxed-Up on Increased Activity following Slurry Activity
P-2015-20239	Automatic Box-Up: Unit Boxed-Up on Increased Activity following Slurry Activity
P-2015-20458	Unit 4 Shutdown due to Turbine Trip
P-2015-21579	Safeguards: Temporary Loss of Power to IAEA Spent Bundle Counter

Quarter: 2015Q4

P-2015-20746	Unposted Hazard: Gamma dose rates > 2.5 mrem/h Measured Exterior to UPP
P-2015-21633	Licence Condition Non-compliance: Station Below Minimum Complement
P-2015-23010	Technical Operability Evaluation Initiated Regarding Class II Batteries
P-2015-24464	Technical Operability Evaluation Initiated Regarding Impact of Low EWS Flow
P-2015-25919	System Unavailable: Does Not Meet Design Intent Impairment Declared as Two ELPSW Pumps were Unavailable
P-2015-26104	Apparent Missed Test: Fire Protection Test not done by Due Date
P-2015-28304	External Event: Smoke Observed from Main Security Building Ceiling
P-2015-28362	Apparent Licence Condition Non-compliance: Inventory Change Document not sent to CNSC within Time Period specified in RD-336
P-2015-28382	Automatic Box-Up: Unit Boxed-Up on Increased Activity while Venting Helium Storage Tank
P-2015-28419	Automatic Box-Up: Unit Boxed-Up on Increased Activity while Venting Helium Storage Tank