

## Western Waste Management Facility CNSC Reportable Events (Q1 2015)

Date of Occurrence	Report Number	Event Title
Feb 28, 2015	N-2015-04994	Electrical Supply Breaker for Emergency Lighting Units and Emergency Exit Lights was found open. Lights were inoperable for a period of time.
Feb 15, 2015	N-2015-03749	A number of Emergency lighting Units in the Steam Generator Storage Building and the Retube Component Storage Building failed their yearly 30 minute tests.
Jan 6, 2015	N-2015-00197	Engineering Assessment determined three relief valves from the Weld Cover Gas system had insufficient relieving capacity.

## Pickering Waste Management Facility CNSC Reportable Events (Q1 2015)

Date of Occurrence	Report Number	Event Title
Feb 3, 2015	N-2015-04688	Two fire protection system air relief valves were discovered to have a maximum operating pressure lower than the system design.

## Darlington Waste Management Facility CNSC Reportable Events (Q1 2015)

Date of Occurrence	Report Number	Event Title
March 23, 2015	N-2015-06932	Standby generator Class III power system impairment.
Feb 17, 2015	N-2015-03885	Firewater system backflow preventers found frozen.
Jan 22, 2015	N-2015-00937	Fire extinguishers found in service past their replacement date.

## Western Waste Management Facility CNSC Reportable Events (Q2 2015)

Date of Occurrence	Report Number	Event Title
May 19, 2015	N-2015-13376	CNSC formal acceptance for modification to National Fire Protection Association Standard 12 requirements for Carbon Dioxide Extinguishing Systems not obtained for Low Level Storage Buildings #1-9.
May 15, 2015	N-2015-11365	Emergency Lighting fixtures failed the 30 minute illumination test in Low Level Storage Building #11.
May 7, 2015	N-2015-10926	Annual Test on Emergency Lighting for Low Level Storage Buildings #11-14 not performed within the time frame required.
April 21, 2015	N-2015-09186	Emergency Lighting fixtures failed the 30 minute illumination test in Low Level Storage Buildings #2, 7, 8, and 10.
April 17, 2015	N-2015-09076	Western Used Fuel Dry Storage Facility fire hoses were not replaced within the five year replacement requirement.

## Pickering Waste Management Facility CNSC Reportable Events (Q2 2015)

Date of Occurrence	Report Number	Event Title
None		

## Darlington Waste Management Facility CNSC Reportable Events (Q2 2015)

Date of Occurrence	Report Number	Event Title
June 22, 2015	N-2015-14458	Fire detection system impairment due to damaged linear heat detector cables during construction of new storage building.
May 6, 2015	N-2015-10242	Emergency lighting units did not pass an annual test to provide illumination for a full thirty minutes on battery power supply.

Western Waste Management Facility CNSC Reportable Events (Q3 2015)

Date of Occurrence	Report Number	Event Title
None		

Pickering Waste Management Facility CNSC Reportable Events (Q3 2015)

Date of Occurrence	Report Number	Event Title
None		

Darlington Waste Management Facility CNSC Reportable Events (Q3 2015)

Date of Occurrence	Report Number	Event Title
None		

## Western Waste Management Facility CNSC Reportable Events (Q4 2015)

Date of Occurrence	Report Number	Event Title
None		

## Pickering Waste Management Facility CNSC Reportable Events (Q4 2015)

Date of Occurrence	Report Number	Event Title
None		

## Darlington Waste Management Facility CNSC Reportable Events (Q4 2015)

Date of Occurrence	Report Number	Event Title
October 9, 2015	N-2015-23808	Failed to complete post-maintenance testing on fire detection communication lines for the Retube Waste Storage Building.